



Main house - South facing - metal

photo taken fall 2025



Side entrance - metal / cedar shake

photos taken Fall 2025



rear pool house - asphalt
shingles

photo taken fall 2021